**CDM 2015:** 

to,

CDM2020????

# Newcastle Construction Safety Group Friday 29<sup>th</sup> March 2019











CDM 2015


Good / Bad / Worked / Not Worked

Lazy Underbelly - RAMS


Solutions / Improvements











In our (me and Summers-Inman) experience – CDM fails when:-

Lack of communication and coordination


Lack of clarity over responsibility / accountability

CDM is separate and not integral part of business / approach

Lack of CDM in change control process

Lazy underbelly – RAMS & duty holders

Principal designer appointed late



# **Pressure**

Ignorance





# **Copy and Paste**






Incompetence



Resources



# Method Statement

"Remove and replace rooflights"



#### Construction Phase Plan

- All scaffolding and staircases to be modified to Summers Inman recommendations.
- Toe boards to be fitted to handrail at both eaves.
- Extra fittings to handrail standards to ensure stability.
- No gaps greater then 470mm to all of the above.
- Nets fitted to every accessible area as an extra precaution.
- . Harnesses to be worn at all times when on roof, clipped onto handrail.
- Scissor lift to be permanently on site for loading unloading and for rescue plan.
- Area below works to be cordoned off so as any bolts falling cannot land on anyone, larger items will be trapped in the nets.
- Any items that cannot be safely removed will be left in the nets and removed when the nets are dismantled.
- Any asbestos items will be double bagged and removed from site by disposed of at a licensed waste disposal site.
- are licenced waste carriers with the Environment Agency
- Weekly visits will be made by management to ensure smooth and safe progress
  of work.
- Weekly meeting to be arranged with management to agree area of works for the week and revised as and when necessary to suit both parties by having a brief meeting each morning as work progresses.
- Copies of all relevant qualifications, C.S.C.S etc., will be provided before works commence when operatives names will be confirmed.
- Evidence of operatives competence/experience to be provided before works commence
- Operatives to visually inspect scaffold each day and keep a written record.
- Scaffolder to visit site weekly to sign off as per H.S.E guidelines.
- The rooflights to be fitted are Class I fire rated to meet current building regulations but
  are not non fragile as the complete roof is fragile and therefore nowhere should be
  walked on without sufficient stagings to spread the load.

# Risk Assessment

• 16 pages – **Genericness** – including excavations and shoring but no WAH rescue plan!

#### METHOD STATEMENT

1 of 2

n	-		44	
u	•	Lς	E+1	

14 March 2019

#### Contractor:

#### Contact:

#### Project:

## Supervisor/Foreman: Admitact

Employees expected on site: 4

#### Introduction

As is general practice within the company most repairs, refurbishment and building work will be carried out by its own employees. Should external contractors be required they will have been checked for competency. They will be asked to provide a copy of their Health and Safety Policy Statements (if applicable), appropriate Risk Assessments/Method Statements and relevant insurance cover. They may also be asked to demonstrate their ability to carry out any such work.

#### Scope of Works:

Repairs and decoration of box sash windows

Consultation will have been made with any secondary contractor's where necessary, with an agreement to follow any site instructions.

> recognises and accepts its responsibility as an employer for providing a safe and working environment for all its employees.

The company will take all steps within its power to meet this responsibility, paying particular attention to the provision and maintenance of;-

Plant, equipment and systems of work that is safe Safe arrangements for the use, handling, storage and transport of articles and substances A healthy working environment A safe place of work and safe access Warning signage to in be place

Our work on site will commence on

2 of 2

Health and Safety and Associated Risks;

Specific Hazards -

Working at Height

Hazardous Operations;

Risk Assessments provided for:

Working at Heights

Manual Handling

Power tools

Painting

All plant and equipment used will be checked prior to use and any training required will be given. All portable appliances will conform to current Portable Appliance Testing standards.

Protective and safety equipment for our operatives use has been issued and signed for by all our employees in accordance with the requirements under the PPE Regulation.

Safety clothing and footwear to be worn at all times

Goggles to be used when there is any chance of material entering into the eyes

Gloves and dust masks

All debris resulting from our work will be cleared up on a nightly basis, bagged and removed from site to skips

Power tools to be checked prior to use

Manual handling tool box talk to be adhered to

Ensure appropriate COSHH sheets adhered to

For and on behalf of:

Dated 14 March 2019

#### Specific Legislation/Guidance

The following has been utilised in preparing this assessment:

- Reporting of Injuries, Diseases and Dangerous Occurrences Regulations 2013 (RIDDOR)
- Health & Safety Act Current Amended 2013
- Health and Safety at Work etc. Act 1974 Current Amended 2013
- HSE Regulations 2007 Approved Code of Practice L144
- Health & Safety Enforcement Authority Regulations 1998
- The Health & Safety Law for Employees Regulations 2012
- The Employers' Liability (Compulsory Insurance) Act 1969
- The Health & Safety (First Aid) Regulations 2011
- Construction (Design Management Regulations) 2007
- Construction (Health Safety & Welfare) Regulations 2007
- Health & Safety in Construction HSG 150
- Health & Safety Control of Asbestos Regulations 2012
- Health & Safety General Product Safety Regulations 1994
- Managing for Health & Safety HSG65
- Noise at Work Regulations 2008
- Manual Handling Operations Regulations 1992
- The Personal Protective Equipment at Work Regulations 1992
- The Provision and Use of Work Equipment Regulations 1998
- Building Regulations
- Working At Height Regulations 2005/2007 (As Amended)
- Control of Substances Hazardous to Health Regulations 2002 Sixth Edition

#### Additional assessments required

#### 7. Implementation & Monitoring

This assessment has been prepared by

This assessment and safe system of work has been made specific for this particular project by

Name (

Position: Director

Date 14.3.19

The implementation and monitoring of this assessment during this project shall be undertaken by Site Supervisor



# **RISK ASSESSMENT**

			Location of Task:	Front Elevation			
Description of Task:	Scaffold Erection and Dism	nantling				Page:	1 of 13
Hazardous Agents	Significant Risk?	Critical Activities	Significa Risks?	Hazardous ( o	nsequences	Signifi	cant Risks?
Oxidants		Work at Height	✓	Environmenta	l Discharge		
Inert Gas		Work over Water	1	Fire/Explosion	1		
Flammable Gas/Vapour		Manual Handling	1	Primary Struc	tural Damage		
Toxic Gas/Chemicals/Va	pour	Mechanical Lifting (vehicles, crane	25)	Secondary Str	uctural Damage		
Corrosives		Lifting Equipment		Loss of Stabili	ty		
Other Hazardous Chemi	icals	Machinery (moving parts, ejection	n)	Damage to Eq	ulpment		
Fuel Oil		Power Tools		Injury to Perso	onnel		✓
Lubricant Oil		Hand Tools	1	Fatal Injury			1
Biological Agents		Welding / Cutting		Asphyxiation			
Noise		Water Jetting / Grit Blasting		Drowning			
Vibration		Excavation		Skin Sensitisal	tion		
Electrical Energy		Confined Space Entry	1	Corrosive Inju	iry		
Static Electricity		Process Isolation		Toxic Effect			
Radiation		Electrical Isolation		Radiation Ove	erdose		
Temperature / Ventilation	on	Work on Safety Systems		Electric Shock			
Pressure		Breaking Containment					
Illumination	✓	Pressure/Leak Testing					

		the state of the s
Date: 17-02-2019		
Prepared By:	Position:	Signature:
Checked By:	Position:	Signature:

12.METHOD STAT	EMENT REVIEW:		
		·······	
Name		Signature	Date
0012.	17th Febru	ary 2019, Issue 1	REV:1

School asbestos fine: Failures lead to over £100,000 in fines

The company appointed a subcontractor to remove the suspended ceilings on its behalf but provided only a generic risk assessment and method statement which failed to identify important information, including the asbestos risk.

# Worker fractured spine in roof fall on construction site

The <u>HSE</u>'s investigation revealed that, while a risk assessment and method statement were in place to remove the roof sheets from below, this method was then changed to remove them from above. It was during this process that the employee fell through a roof sheet.

# Suspended sentence for rope access boss

The HSE's investigation found that the person put in charge of planning and supervising the work had never worked on a fragile roof before. It was also found that the method statement prepared was inadequate as rope access is generally not suitable for use on fragile roofs.

Over £2m in fines after worker breaks leg in trench

After the accident, John Henry & Sons (Civil Engineers) Ltd, backdated the method statement to give the impression that it was signed by the workers prior to the trench collapsing

## Sentence after worker injured at prison

An investigation by the Health and Safety Executive (HSE) into the incident found that Longcross ConstructionLimited, Fewell Engineering and SJT Site Management Limited, all failed to prepare suitable and sufficient Risk assessments and method statements for the operation.

£200k fine for Glasgow construction firm following fatality

Morris & Spottiswood Ltd had failed to review the risk assessments and method statements submitted by the steelwork sub-contractor for the task and had failed to establish and maintain an exclusion zone around the steelwork while erection was being carried out

# Firms ordered to pay over £400k after road worker loses arm

HSE's investigation revealed a series of safety failings on the part of all three companies, including: the risk assessment described a different type of chip spreader than the one used on site;

# Site manager and safety consultant jailed after labourer's death

## The HSE said that:

- •the method statement included information that was copied and pasted from a document relating to a previous basement job undertaken by SIDAY;
- •the method statement was prepared without reference to any temporary works engineer drawings or schemes in relation to the propping and shoring temporary works that would be needed on site. This was to be added by SIDAY at a later date according to the method statement but this did not happen. The method statement was therefore inadequate;



Aps Survey link on future of CDM

https://www.surveymonkey.co.uk/r/J9VSLT2